

Contents

Re: question about oil filter examination	9
Re: question about oil filter examination	10
Prop strike teardown recommendation	10
Removing magnetism from Austenitic Stainless steel	11
High oil temperature in Lycoming and Continental engines	12
Bendix D3000 magneto redundancy	12
Oil Filter Examination - continued	14
Leaning a Carbureted Lycoming or Contintal past Peak	17
I have this problem with my aircraft engine...	17
Inspecting the magneto coil	18
Sealing Aircraft Engine Cases	19
Bastardized AN fittings - Which AN fitting goes into the hole?	20
Use of crush washer on AN Fitting Connections	23
AN Thread Size and AN Fitting Size Chart	23
Hose Problems	24
AD2009-16-03 SAP Cylinder Cracking	25
Bad Valve Seat Job	27
Cessna 152 Poor Idle - Carburetor Foam and Hollow Floats Sb-2	28
Fuel Hose Installation and Electrical Wiring in Aircraft AD2009-15-01	29
Rough Engine on left mag - nothing you do fixes the problem!	29
Stuck Valve Check - Quick, Easy, Inexpensive	31
Should you pump the throttle on a carbureted engine?	32
Do Aftermarket Oil Additives Reduce Wear Metals ?	32

Improvements to the Slick Magneto	33
What is a Finger Doubler?	34
Slick magnetos and propeller strikes	35
Fingerprint Corrosion on Aircraft Products	36
Inspecting High Strength Materials	36
Starters and Worm Gears in Aircraft Piston Engines	37
Alternator Load Dump by the pilot switching off the alternator circ...	39
Rivet Edge Distance	39
Some thoughts on camshaft lobes	41
Preflight Inspection Tip - Inspect the muffler	42
What's wrong with Aircraft Drain Valves?	44
When rings should be replaced on aircraft cylinders?	44
How to properly ground a dual magneto?	45
Hose dash size to Inside Diameter	46
Replacing the Spark Plug Helicoil in Lycoming and Continental Engines	47
Engine Break In	47
Stuck Piston Rings in Lycoming - What to do	49
Can you use a torque wrench to inspect a bolt for proper torque?	50
aircraft battery explosion	52
Increasing Reliability of your Aircraft's Fluid Delivery System	52
Factory New Limits and other Nonsense	53
Should Corrosion Preventive Fluids be used on Riveted Joints?	54
Lycoming Fluctuating Oil Pressure	56
Setting Slick Magneto Point Gap	57

Lycoming camshaft	58
Faulty NTSB Conclusions N9348S	58
Backfiring	60
Lycoming Valve sticking Tip	61
Breaking Studs	61
Lycoming cylinder barrel wear signs	63
Are Aeroquip fittings usable on Stratoflex hose, and vice versa, ar...	64
Spark plug anti-seize	65
Aircraft Vacuum Pump Troubleshooting	65
Introduction to Aircraft O-rings	66
Glazed cylinder and high oil consumption	66
ROTEC radio noise	66
Don't Forget to Inspect the Rocker Arm	67
Replacing Spot Welds with Rivets	68
Field Inspecting Bonded Joints - Problems and Expectations	69
Aircraft Hose Temperature Limitation Warning	70
Inspecting Aircraft Control Cable	70
Engine Balance and the Arms Race	71
Bulkhead Hole Size	73
Comparison of Tube Strength for Common Small Aircraft Tubing	74
Slick Magneto Timing Light Flicker	76
Inexpensive Measuring Stick for Lycoming Pushrods	76
Aluminum Corrosion Penetration as a Function of pH	77
Coarse Thread vs Fine Thread Strength	77
Hydrogen Embrittlement	77

When to Use a Washer	80
Camshaft Lobe Pitting Evaluation	81
Bulkhead Fitting Installation into Aircraft O-Ring Port	82
Aircraft Fuel Flow Transducers - Hose Suggestions and Warnings	83
Beech Marks, Fatigue Failure, and High Compression Pistons	84
Don't Mix your Metals	85
Graphite Lubricants in Aircraft- The Corrosion Potential	86
Continental Cylinder Stud Design	87
Double Flare Tubing	88
Clean and Dry Torque	89
Aircraft Wire Inspection	90
Aircraft Control Cable - Stainless or Galvanized?	92
Stainless Steel Stress Corrosion Cracking - Primer for Aircraft Mec...	93
Aircraft Control Cable - What is it?	95
Monel Safety Wire - When to Use	96
Titanium Limitations in Aircraft Repair	97
Oil Leaks -- It's not the gasket it's the surface	102
Aircraft Engine Age Deterioration	103
Slick Magneto Inspection Tip	106
Propeller blade cracks	108
Aircraft Washer Usage	109
Exhaust Valve Deposits - Concentricity	111
High MP low RPM Continental TSIO520 engine (or Lycoming engines)	113
Aircraft Rivet Hole Fatigue Strength	115

Metal Fatigue, Cracks, and Turbo Mallards	116
How to Properly re-magnetize a magneto rotor magnet?	117
Suspect Un-Airworthiness	118
Aircraft Hose Bonding and Lightning Protection	119
The Aircraft Structural Mechanic (why you deserve a pay raise)	121
B-nut Torque and Loosening	122
AN Bolt Head Design	123
AN Nut Face Design	124
Unsafe Engineering - Use of NPT Ports in Critical Aircraft Systems	126
Hose Flap	127
Pilot Description of Preignition	128
Tightening Rubber Gaskets	130
Pilot Description of Broken Impulse Coupling Spring	131
Torque Wrench - Accuracy and Precision	132
Nature of Efficient Design	133
Cracks in Aircraft Structures	134
Lobing and other Low Frequency Form Error In Aircraft Piston Engines	135
Magneto Test Bench Electrode Design	137
Lycoming or Continental Counterweight Detuning	138
Preventing Oil Leaks	140
Fits and Limits	141
Oil Leaks Across All-Metal Joints	142
Crack Detection Using the Unaided Eye	143
Measurement Errors and Challenges for Mechanics	151
Aircraft vs Commercial Wire Terminals	161

Cleaning Aluminum without creating Corrosion	163
Inadequate Guidance	166
Aircraft Structural Integrity - The 5 Threats	166
What is Crankshaft Runout	167
High oil temperature on Lycoming aircraft engine	170
Installing Aircraft Hose - The 10 Rules	170
Valve Leakage - serial offender	171
Wear Evaluation of the Camshaft Follower Bore	172
Damage Tolerance doesn't work without Detection	174
How to deal with Intimidation for the Aircraft Mechanic	176
How to fix Aircraft Compass Errors	178
How to Diagnose and Fix Rocker Shaft and Bushing Wear	180
Trouble Shooting - The Question to Ask Before you Begin	182
Why Metal Gaskets Leak	183
Aircraft Hardware compared to Industrial Hardware	184
Preventing vibration induced bolt loosening	185
Does the bolt loosen slightly after you torque the bolt?	186
Reusing Locknuts	187
Aircraft Screw Countersink Angle	189
How Antiseize Changes Bolt Torque	190
Is it possible to use differences in CHT change when leaning to fin...	191

Re: question about oil filter examination

John,

I have read your knowledge base post on oil filter examination and wondered if the author (or other knowledgeable person) could answer a question for me.

I routinely open my filters. Under casual observation nothing much is evident. The last couple of times I looked a little closer than usual and in bright sunlight. In the bright light I can see scattered microscopic shiny bits. They are so tiny you wouldn't see them other than by their reflection. I have been told that this represents an inconsequential finding, possibly microscopic bits from plating - normal wear finding. Would you agree?

I also find little bits of debris here and there, non-metallic in appearance and non-magnetic. It has the appearance of a tiny quantity of sand which may be just what it is.

I have not found anything large, magnetic, or otherwise scary looking.

Ultimately my question I suppose is; Should anything at all be visible on the pleats? I would imagine that filtering oil through there for 40-50 hours you gonna find something. That's what it's there for, right?

Thanks
Steve

On my other web site I mention how to use sunlight to see microscopic particles in the oil http://www.icancutter.com/how_to_inspect.htm. These might be small bits of bearing material.

Often with mechanics I don't agree with their theory but I do agree with their actions because often it is based on years of practical experience.

It is not normal for parts in an engine to shed metal particles. Possibly during initial break-in (when you have surfaces getting to know one another) you can have a small amount of particles. From then on normal wear on surfaces does not generate particles. So much for theory. Now what do you do about it?

If the particles are very small and not many then typically the answer is to keep checking and make sure it doesn't get worse.

For your stuff that looks like sand. Try to squish the particles between two pieces of glass or your finger nails. Sand will not squish and will scratch the glass or your finger nail.

By examining the pleats you aren't going to find cam lobe or cam follower material in the early stages of failure. Better to rinse the pleats with solvent and a toothbrush. Drain the liquid through a coffee filter and let dry. Place a magnet under the coffee filter and move all of the iron to one side. If there is enough fuzz sticking to your magnet to cover the end of a stick magnet then inspect the cam lobe and follower. You will get a much better idea as to the amount of stuff that is in your filter using this method.

Re: question about oil filter examination

Thanks very much for your help John.

Here's an update:

In advance of reading your response I actually rinsed off a few pleats into a glass container with solvent.

Note that I picked pleats where small visible accumulations had gathered which I suspect relates to oil flow patterns through the filter.

I then dried the material which consisted of a few very tiny particles of varying color - tan, brown, gray.

None of it is magnetic.

I then took it out and squished it between my fingernails. It all mashes up effortlessly into a fine powder.

My feeling is therefore that this represent tiny bits of carbon or combustion products.

I think the shiny things I'm looking at are microscopic gray carbon bits.

Steve,

Black and gray particles that you can squish between your fingernails are pieces of carbon, sludge and lead oxides and are normal.

Small shiny bits you can spread them onto a microscopic slide and add a drop of Drano mixed with water. Look carefully under the microscope. If it is aluminum it will start to fizzle and dissolve.

Prop strike teardown recommendation

To answer the question "should the engine have been torn down for a more complete inspection"?

My recommendation has always been to do a tear down inspection for the following reasons:

1. After a prop strike there is rightful concern about the airworthiness of the engine. This concern can only be answered by inspection and not by hope, prayer, or opinion.

2. Having a shop that has performed approximately 1 prop strike inspection each month for some 20 years, I still cannot tell you which prop strikes cause damage and which ones don't without an inspection. This has taught me that the perceived "severity" of the propeller strike is not a criteria for deciding which engines should be inspected and which ones need no inspection.

3. I personally didn't tear down my engine after I hit the towbar with the propeller and sent it flying across the airport. But then we did one on a Navajo that hit a plastic caution cone that had damage -

4. Engine mounts can also be damaged. That said, my opinion is based on my personal experience and others have views that conflict with mine based on their experience and judgement. I could be wrong.

I have spend many year pondering how to inspect the engine without tearing it down and I have never come up with an adequate method. Your question as to signs to look for - I don't know.

Removing magnetism from Austenitic Stainless steel

I bought some 304 stainless steel tubing for building a fuel cell and found that even though it was touted as being austenitic, it had a magnetic field down the welded seam (nowhere else). I had tested the tubes with a neodymium magnet and saw where the field was. Will your degausser remove the magnetic field?

The degausser will not prevent the austenitic stainless from being magnetic. It will remove magnetic fields excepting the earth's magnetic field.

Austenitic is slightly magnetic when cold worked. In the fully annealed condition it is non-magnetic.

Any austenitic (300 series) stainless steel which is magnetic can be returned to non-magnetic condition by stress relieving to 700-800 degrees C. It then reverts back to its fully annealed condition and is softer and weaker. There may be other issues with annealing so the best thing to do would be to engage a metallurgist.

The degausser will remove an artificial magnetic field from a iron object, leaving just the earth's magnetic field. By testing with a magnet you have probably slightly magnetized the weld area (stressed area).

High oil temperature in Lycoming and Continental engines



*Hi John,
Here are the photos of my home made oil cooler for the Continental O-300. It actually takes about 15 degrees out of the oil on these hot summer Texas days.*

Take a close look. This is a Rapco vacuum pump cooling shroud!



This customer installed the Rapco vacuum pump cooling shroud around his oil filter. Neat idea and it reduced oil temperature by 15 degrees!

Bendix D3000 magneto redundancy

John, I purchased and read your magneto book, which I found informative and interesting. After reading the book, I do have two questions I'm wondering if you could answer given your experience with magnetos.

1. Our Cardinal has the dual magneto, although I am considering a conversion to a non-D at the upcoming overhaul. My question regards redundancy: what internal elements are common to the two magnetos within the D housing?

Do they only share a common drive shaft (and gear), or are any other electromechanical components shared - e.g., cam, magnets, etc.? Do you know of any source where I could see internal photos or mechanical or cutaway drawings of the D3000 magneto so I could better understand its design?

Yes, the maintenance/overhaul manual for this magneto. About the only parts that are truly redundant is the coil, points, and capacitor.

The D3000 magneto is a good magneto, easy to work on and reliable. Like any device it has its limitations. Follow the maintenance/overhaul manual, service bulletins and airworthiness directives.

The following three areas should be well understood, respected and maintained, as all have caused fatal aircraft accidents:

- Impulse coupling spring (part number 10-51324)
- Hold-down clamps
- Cam retaining screw

Impulse Coupling Spring: Magneto Impulse coupling spring

Breakage retards timing causing complete loss of engine power. Cessna 172N N738BC ditched at sea with 2 fatalities. On any magneto the impulse area sometimes gets rusty from condensation. The impulse spring gets tiny rust pits that create stress corrosion cracking. There is no warning - it just breaks. With two magnetos you lose timing but you can turn the bad magneto off; with the D3000 magneto the broken spring retards the timing on **both** magnetos and you lose power.

Follow TCM's instructions and recommendations to the letter in regards to inspecting and replacing the impulse spring. Personally, if I lived in a corrosive area I would replace it every year.

Hold-down Clamps:

See my article at <http://www.sacskyranch.com/eng410.htm>

Cam Retaining Screw: "Everything hangs on this connection"

Here is a copy of an email I received some time ago from Germany:

A pilot came to an aircraft workshop with the problem, that the engine did not start well and did not reach more the 2200 RPM. (Cessna 170 N engine Lyc.O-320-H2AD SNR L-8408-76T)



The workshop made -a test run on ground:

*the engine rpm drop was 120-130 rpm.-
The different pressure in the cylinders was 1.)80/78; 2.)80/79; 3.)80/78; 4.)80/77.-
The intake tube of the Cylinder No 3 was leaky -it was renewed.-
The timing of the ignitions examined and adjusted.-
The air intake filter was dirty and cleaned -
The following ground check did show no*

problems: rpm drop 70-80 rpm max rpm 2320 rpm.



After this the aircraft made a take off and crashed immediately in the ground, as the engine lost power.

The investigation did show, that the screw (Fig 1-14 D-3000 Magneto manual) was loose and so the cam breaker could turn on the cone.

Magneto cam retaining screw D-2000, D-

3000 points and cam

The problem here is that the mechanic did not order a new cam screw and re-used the old one. You loosen this screw when you adjust internal timing. This screw is a self-locking screw that uses a nylon patch on the threads. The locking effectiveness is poor if re-used. Continental says to replace it with a new one. Follow the factory instructions - accept no deviation or alternative methods of compliance.

Continental (Bendix) has addressed each one of these areas in their maintenance manual. Personally, if the mechanic did not have the maintenance manual for the D3000 in hand I would not let him touch the magneto.

There is an interesting discussion of this screw and the problems associated with installing it that I highly recommend be read by anyone working on this magneto. http://www.aaib.dft.gov.uk/cms_resources/Mooney%20Aircraft%20Corporation%20M20J,%20G-EKMW%2011-06.pdf

Oil Filter Examination - continued



John,

So, being a reformed lab-rat myself, I set up a little scope and had a look at my filter washings. Here's a little show if you have a minute to view and comment. I realize there are services that will do this and I will likely send the next filter to them to see what they say but I thought you might like to see what I came up with...Incidentally, under magnification, most of the tiny reflectivity's I was seeing on the filter in the sun represented light reflecting off of oil dampened flat surfaces of a variety of tiny non-metallic looking debris. My stereo scope:



I washed one half of the total available oil filter, after cutting it out, with solvent into a cup. For reference, the cup's base diameter is about 1.5 inches. Here's all that I got in washing:

Under magnification it looks like this (20-40X)



I threw in a hair (ouch!) for reference: